

#### ECAD WORKGROUP MANAGER PRE-INSTALLATION SETUP


Set the **JAVA\_HOME** in your environment variables (example: JAVA\_HOME=c:\j2sdk1.4.2\_15). **Note**: The JAVA directory *should not* have spaces in the path (example: c:\Program Files\java). The following three pictures illustrate this step.







Launch a command window by going to "Start" and then "Run." Key in "cmd" in the field, and then select "OK."



Go to your Java "**jre\bin**" directory. **Note**: You may need to download this Java software if it is not on your machine.

```
Microsoft Windows XP [Version 5.1.2600]

(C) Copyright 1985-2001 Microsoft Corp.

H:\>keytool' is not recognized as an internal or external command, operable program or batch file.

H:\>c:

C:\WINNT>cd..\j*

C:\j2sdk1.4.2_15>cd bin

C:\j2sdk1.4.2_15\bin>di
'di' is not recognized as an internal or external command, operable program or batch file.

C:\j2sdk1.4.2_15\bin>cd ..\jre

C:\j2sdk1.4.2_15\bin>cd ..\jre

C:\j2sdk1.4.2_15\bin>cd bin

C:\j2sdk1.4.2_15\bin>cd bin
```

Create the **jssecacerts** keystore and add the client certificate. This process will require you to create an alias and a password.

Ensure the provided certificate (provided by DDMS Support) is located in the **c:\ptc\sslcertificate** directory.

To create this keystore type the following in the command prompt: keytool –import –keystore ..\lib\security\jssecacerts –alias iecteam –storetype jks –file c:\ptc\sslcertificate\iec\_030807.crt

```
Microsoft Windows XP [Version 5.1.2600]
(C) Copyright 1985-2001 Microsoft Corp.

H:\Nkeytool
'keytool' is not recognized as an internal or external command,
operable program or batch file.

H:\Nc:
C:\WINNT\cd..\j*
C:\j2sdk1.4.2_15\cd bin
C:\j2sdk1.4.2_15\bin\namegad as an internal or external command,
operable program or batch file.

C:\j2sdk1.4.2_15\bin\namegad as an internal or external command,
operable program or batch file.

C:\j2sdk1.4.2_15\bin\namegad a.\jre
C:\j2sdk1.4.2_15\bin\namegad a.\jre
C:\j2sdk1.4.2_15\bin\namegad bin
C:\j2sdk1.4.2_15\jre\cd bin
C:\j2sdk1.4.2_15\jre\bin\namegad bin
C:\j2sdk1.4.2_15\jre\bin\namegad bin
C:\j2sdk1.4.2_15\jre\bin\namegad bin
C:\j2sdk1.4.2_15\jre\bin\namegad bin\namegad c.\lib\security\jssecacerts -alias iesbrownma2 -s
toretype jks -file c:\ptc\sslcertificate\iec_030807.crt
```

#### Enter "iecteam" for the password.

#### Enter "**ves**" to trust the certificate.

```
St C\WINNT\system32\cmd.exe - keytool - import - keystore _\lib\security\jssecacerts - alias iesbrownma2 - storetype Jks - file c\ptc___ _ _ _ X

Microsoft Windows XP [Uersion 5.1.2600]

(C) Copyright 1985-2001 Microsoft Corp.

H:\\keytool
'keytool' is not recognized as an internal or external command,
operable program or batch file.

H:\\c:

C:\WINNT\cd..\j*

C:\j2sdk1.4.2_15\bin\cd
i'di' is not recognized as an internal or external command,
operable program or batch file.

C:\j2sdk1.4.2_15\bin\cd
..\jre

C:\j2sdk1.4.2_15\bin\cd
..\jre

C:\j2sdk1.4.2_15\pin\cd
..\jre
```

Once these steps are completed, you are ready to install the ECAD workgroup manager from the DDMS site.


#### ECAD WORKGROUP MANAGER INSTALLATION

Make sure that you have installed the **InterComm Expert** software prior to loading the workgroup manager.


Go to your **Home Utilities** page and select ECAD Tools.





After selecting the software agreement choice, select the ECAD workgroup manager download link.




Select the installer for Windows. Follow the prompts for the remaining parts of the install.












You will need to select your required ECAD tools.






Enter the url address of the server.




DDMS SUPPORT GROUP

3/5/2008 Page 9 of 10



Complete the installation.



3/5/2008 Page 10 of 10